

# CHAPTER 1: INTRODUCTION TO PHYSICS

## 1.1 Physical Quantities

### 1.1.1 Quantities and Units

**Physical quantity:** A property ascribed to phenomena, objects, or substances that can be quantified

**Base quantity:** Physical quantity that cannot be defined or derived from any other physical quantity

**Derived quantity:** Physical quantity obtained through a combination of base quantities via multiplication or division

The five base quantities:

	Quantity	Symbol	SI Units	Units (Symbol)
1.	Length	$l$	meter	m
2.	Mass	$m$	kilogram	kg
3.	Time	$t$	second	s
4.	Temperature	$T$	Kelvin	K
5.	Electric current	$I$	Ampere	A

### 1.1.2 Scientific Notation (Standard Form)

$$A \times 10^n$$

where  $A \leq 1 < 10$  and  $n = \text{integer}$

The value of A should always be rounded to 3 or 4 significant numbers.


### 1.1.3 Prefixes

Prefix	Value	Standard form	$10^n$ where $n$ is	Symbol
Tera	1 000 000 000 000	$10^{12}$	12	T
Giga	1 000 000 000	$10^9$	9	G
Mega	1 000 000	$10^6$	6	M
Kilo	1 000	$10^3$	3	k
Hecto	100	$10^2$	2	h
Deca	10	$10^1$	1	da
Deci	0.1	$10^{-1}$	-1	d
Centi	0.01	$10^{-2}$	-2	c
Milli	0.001	$10^{-3}$	-3	m
Micro	0.000 001	$10^{-6}$	-6	$\mu$
Nano	0.000 000 001	$10^{-9}$	-9	n
Pico	0.000 000 000 001	$10^{-12}$	-12	p

1.2 Scalar and Vector Quantities

Scalar Quantities	Vector Quantities
Physical quantities with <b>magnitude</b> only	Physical quantities with <b>magnitude</b> and <b>direction</b>
<b>EXAMPLES</b>	
Distance	Displacement
Speed	Velocity

**Example: Distance vs Displacement**



Fauziah travelled from Kuala Lumpur to Kangar, a distance of 507 km. After that she continued her journey to Butterworth, a distance of 138 km. From Butterworth, Fauziah then travelled back to Kuala Lumpur, a distance of 369 km.


**Distance is the TOTAL DISTANCE TRAVELLED BY THE OBJECT.**

Therefore, distance = 507 + 138 + 369 = **1 014km**

**Displacement is the DIRECT DISTANCE BETWEEN THE STARTING AND ENDING POINT.**

Because Fauziah's final location is the same as her starting location, her final displacement = **0 km**

**Example: Speed vs Velocity**



Although both cars are traveling at the same **speed**, i.e. 60 km/h, they are traveling at different **velocities** because the directions are different.


**1.3 Measurements**

**1.3.1 Precision, Accuracy and Sensitivity**


Precision	Accuracy	Sensitivity
The degree of uniformity of reproducibility of the measurements (consistency)	The degree of closeness of the measurements to the true or accepted value	The ability of a measuring instrument to detect small changes of the physical quantity measured
To increase precision: <ul style="list-style-type: none"> <li>- use a magnifying glass when reading the scale</li> <li>- avoid parallax errors</li> </ul>	To increase accuracy: <ul style="list-style-type: none"> <li>- use more sensitive equipment</li> <li>- repeat readings taken</li> <li>- avoid parallax errors</li> <li>- avoid zero errors or end edge errors</li> </ul>	To increase sensitivity of a mercury thermometer: <ul style="list-style-type: none"> <li>- thinner wall of bulb</li> <li>- narrower capillary tube</li> <li>- smaller bulb size</li> <li>- thicker wall of glass tube</li> </ul>

**1.3.2 Measuring Apparatus**

Vernier calipers ( $\pm 0.01\text{cm}$ )




Micrometer screw gauge ( $\pm 0.01\text{mm}$ )




1.3.3 Errors

Systematic Errors	Random Errors
Systematic errors are errors that can consistently affect readings. It <i>cannot be reduced</i> by taking the average of multiple readings.	Random errors happen when one reading deviates from the others. It <i>can be reduced</i> by taking the average from multiple readings.
Systematic errors are usually caused by errors within the measuring instrument. For example: <ul style="list-style-type: none"> <li>• Zero errors</li> <li>• End error</li> <li>• Incorrect scale calibration</li> </ul>	Examples: <ul style="list-style-type: none"> <li>• Parallax errors</li> <li>• Unavoidable small changes in the surrounding</li> <li>• Outside disturbances that cannot be taken into account</li> <li>• Lack of sensitivity of the measuring instruments</li> <li>• Human errors, e.g:                             <ul style="list-style-type: none"> <li>○ Counted wrong number of oscillations</li> <li>○ Readings with inconsistent time intervals</li> <li>○ Volume of liquid was measured after some was unknowingly and unintentionally spilt</li> </ul> </li> </ul>

1.4 Scientific Investigation




### Using vernier calipers:



Vernier Scale

The length of the vernier scale is equal to 0.9 cm. There are **ten** divisions on the vernier scale, so the difference between one division on the main scale and one division on the vernier scale is **0.01 cm**

Therefore, the **sensitivity** of a vernier caliper is **0.01 cm**




#### How to make a reading:


- First, note down the value on the main scale just before the '0' mark on the vernier scale.
- Next, observe which mark on the vernier scale is in line with the main scale.

**Reading the zero error values on vernier calipers:**

When the jaws are closed: If the '0' on the vernier scale is *after* the '0' on the main scale, this is a **positive zero error**. The value is obtained by taking the reading from left to right.



When the jaws are closed: If the '0' on the vernier scale is *before* the '0' on the main scale, this is a **negative zero error**. The value is obtained by taking the reading from right to left.



**Actual reading = Reading taken – zero error**

For example, if the reading taken is 0.64 cm:


If the zero error is 0.02 cm, **actual reading =  $0.64 - 0.02 = 0.66$  cm**

If the zero error is -0.08 cm, **actual reading =  $0.64 - (-0.08) = 0.72$  cm**

## Using a micrometer screw gauge:

Every marking here represents integer INCREMENTS

Therefore, the **sensitivity** of a micrometer screw gauge is **0.01 mm**




A full turn of the thimble is equal to **0.5 mm**

Every marking here represents 0.5 mm after the integer increments

### How to take a reading:


- Record the marking on the sleeve just before the thimble
- Observe the marking on the thimble that is in line with the middle line on the sleeve



Reading  
 = 6.0 + 0.22  
 = **6.22 mm**




Reading the zero error values on a micrometer screw gauge:



When the anvil and spindle are closed: If the '0' marking on the main scale is visible and the position of the thimble is *after* the '0' marking, this is a **positive zero error**. The value is taken by reading it upwards.


Zero error = **+0.01 mm**



When the anvil and spindle are closed: If the '0' marking on the main scale is not visible and the position of the thimble is *before* the '0' marking, this is a **negative zero error**. The value is taken by reading it downwards.

Zero error = **-0.01 mm**

END OF CHAPTER

if you like these notes... like us on facebook  
 [www.facebook.com/physicsrox](http://www.facebook.com/physicsrox)